CESA: 01 Number of schools reported for CESA 01: 389

Which best describes the location of your school building?

159	40.87%	Large Central City (Population greater than 400,000 and density greater than 6,000.)	
-----	--------	--	--

77 19.79% Mid-Size Central City (Population less than 400,000 and density less than 6,000.)

145 37.28% Urban Fringe of Large City (Defined as urban by the Census Bureau.)

0.00% Urban Fringe of Mid-Size City (Defined as urban by the Census Bureau.)

0 0.00% Large Town (Population greater than or equal to 25,000.)

0 0.00% Small Town (Population less than 25,000 and greater than or equal to 2,500.)

8 2.06% Rural (Population less than 2,500 and coded rural by the Census Bureau.)

A. PHYSICAL STRUCTURE AND MECHANICAL FEATURES

4. When was the school originally constructed?

Pre-1900	23	5.91%	1930-1939	24	6.17%	1970-1979	29	7.46%
1900-1909	15	3.86%	1940-1949	7	1.80%	1980-1989	2	0.51%
1910-1919	28	7.20%	1950-1959	102	26.22%	1990-1999	20	5.14%
1920-1929	44	11.31%	1960-1969	95	24.42%		-	

5. In your opinion, is this school building overcrowded?

Yes 128 **32.90%** No 261 **67.10%**

6. If the original building has been renovated or had additions, when was the most recent, MAJOR renovation or addition?

No Renovation	125	32.13%	1940-1949	3	0.77%	1970-1979	21	5.40%
Before 1930	17	4.37%	1950-1959	34	8.74%	1980-1989	40	10.28%
1930-1939	0	0.00%	1960-1969	55	14.14%	1000_1000	94	24 16%

7. How many total square feet does the original building have?

Minimum: 5,000 Maximum: 447,130 Median: 49,651 Average: 77,908

8. If the building has been renovated or added on to, how many total square feet exist now?

Minimum: 11,979 Maximum: 870,003 Median: 67,236 Average: 103,948

9. How many portable classrooms were in use during the 1998-99 school year?

Number of schools reporting the use of portable classrooms: 19

Minimum: 1 Maximum: 20 Median: 2 Average: 4

10. Does the school accommodate any of its students in instructional facilities located OFF-SITE?

Yes 28 7.20% No 361 92.80%

11. How many of this school's FTE students are located in OFF-SITE facilities?

Number of schools reporting OFF-SITE facilities: 28

Minimum: 1 Maximum: 200 Median: 23 Average: 48

CESA: 01

Number of schools reported for CESA 01: 389

Definitions for questions #12 and #15:

Excellent: New or easily restorable to "like new" only minimal routine maintenance.

Good: Only routine maintenance or minor repair required.

Adequate: Some preventive maintenance and/or corrective repair required.

Fair: Fails to meet code and functional requirement in some cases; extensive repair.

Poor: Consistent substandard performance; major corrective repair or overhaul.

Replace: Non-operational or significantly substandard performance. Replacement

NA: Not Applicable

12. What is the overall condition of the original buildings and the permanent additions?

	Excellent	Good	Adequate	Fair	Poor	Replace	NA
Original Buildings:	28	85	185	73	9	6	3
	7.20%	21.85%	47.56%	18.77%	2.31%	1.54%	0.77%
Permanent Additions:	45	68	108	49	6	1	112
	11.57%	17.48%	27.76%	12.60%	1.54%	0.26%	28.79%

13. What would be the total cost of all repairs/renovations/modernizations required to put this school's ON-SITE buildings in good overall condition? Number of schools reporting cost for repairs/renovations/modernizations:

CESA Total Costs = \$663,537,720

Minimum:

\$15,000

Maximum: \$15,000,000

Median: \$1,786,450

Average: \$2,303,950

14. On which of the sources listed below is this estimate based? Choose all that apply.

105 12.06% Does not apply--already in good (or better) overall condition.

221 25.37% Facilities inspection/assessment performed within the last three years by licensed professionals.

175 20.09% Repair/renovation/modernization work already being performed/contracted for.

Capital improvement/facilities master plan or schedule. 239 27.44%

104 11.94% My best professional judgement.

27 3.10% Opinions of others.

15. Overall, what is the physical condition of each of the building features listed below for this school's ON-SITE buildings?

	Excellent	Good	Adequate	Fair	Poor	Replace
Roofs:	37	148	93	66	38	7
	9.51%	38.05%	23.91%	16.97%	9.77%	1.80%
Framing, floors, foundations:	37	198	111	33	10	0
	9.51%	50.90%	28.53%	8.48%	2.57%	0.00%
Exterior walls, finishes, windows, doors:	38	112	87	113	32	7
	9.77%	28.79%	22.37%	29.05%	8.23%	1.80%
Interior finishes, trims:	35	214	98	35	4	3
	9.00%	55.01%	25.19%	9.00%	1.03%	0.77%
Plumbing:	28	121	193	31	13	3
	7.20%	31.11%	49.61%	7.97%	3.34%	0.77%
Heating ventilation, air conditioning:	24	114	132	91	23	5
	6.17%	29.31%	33.93%	23.39%	5.91%	1.29%
Electrical power:	34	108	90	88	66	3
	8.74 %	27.76%	23.14%	22.62%	16.97%	0.77 %
Electrical lighting:	39	227	68	48	6	1
	10.03%	58.35%	17.48%	12.34%	1.54%	0.26%
Life safety requirements (e.g., emergency lighting and warning systems, exit signs):	53	238	76	21	1	0
	13.62%	61.18%	19.54%	5.40%	0.26%	0.00%

CESA: 01 Number of schools reported for CESA 01: 389

16. How adequate is your current maintenance budget for keeping your buildings in good overall condition? Very Adequate: 13 3.34% Somewhat Adequate: 252 64.78% Adequate: 84 21.59% 40 Not adequate at all: 10.28% 17. How satisfactory or unsatisfactory is each of the following environmental factors in this school's ON-SITE buildings? Very Satisfactory Satisfactory Unsatisfactory Very Unsatisfactory Lighting: 43 11.05% 307 78.92% 37 2 9.51% 0.51% Heating: 38 9.77% 304 78.15% 44 11.31% 2 0.77% Ventilation: 32 8.23% 3 274 70.44% 20.57% 80 0.77% Indoor air quality: 9.25% 36 277 71.21% 73 18.77% 3 0.77% Acoustics for noise control: 34 8.74% 313 80.46% 42 10.80% 0 0.00% Flexibility of instructional space: 29 7.46% 172 44.22% 181 46.53% 7 1.80% Energy efficiency/conservation: 30 7.71% 205 52.70% 39.59% 154 0 0.00% Physical security of buildings: 31 7.97% 314 80.72% 41 10.54% 3 0.77% Exterior noise: 47 12.08% 2 315 80.98% 25 6.43% 0.51% 18. How many instructional classrooms were in use as of the third Friday in September, 1998? Total number of instructional classrooms reported in use as of the third Friday in September, 1998: 12,737 Minimum: 10 Maximum: 130 Median: 25 33 Average: 19. Does the school building have CENTRAL air conditioning (cools all interior space)? Yes 88 22.62% No 301 77.38% 20. Does this school have air conditioning in instructional classrooms, computer labs, and/or the library? 61 29.47% Yes, in instructional classrooms. 81 39.13% Yes, in computer labs. 65 31.40% Yes, in the library. 21. How many instructional classrooms have air conditioning? Minimum: Maximum: 65 Median: 9 Average: 13 22. Does this school have a separate room for a library/resource/media center? Yes 382 98.20% No 7 1.80% 23. How does the size of your school's library/resource/media center compare with the size of a typical classroom in your building? Smaller: 0.78% About the same size: 59 15.36% Larger: 322 83.85% 24. How many classrooms would fit in the space used for your library/resource/media center? Minimum: Maximum: 3 Median: 2 3 Average: 25. If you have a library/resource/media center, is it staffed by a licensed, professional librarian? Yes 269 70.05% No 115 29.95%

26. What percent time is your library/resource/media center staffed by a licensed, professional librarian?
Number of schools reporting library/resource/media center staffed by licensed, professional librarian:
269

Minimum: 20% Maximum: 100% Median: 100% Average: 88.71%

CESA: 01 Number of schools reported for CESA 01: 389 27. Does this school have a separate room for a parent/family center? Yes 105 26.99% No 284 73.01% 28. How does the size of your school's parent/family center compare with the size of a typical classroom in your building? Smaller: 33 31.43% About the same size: 59 **56.19%** Larger: 13 **12.38%** 29. How many classrooms would fit in the space used for the parent/family center? Minimum: .33 Maximum: 9 Median: 1 Average: 1 **B. SCHOOL SAFETY** 30. Does your school have a "Locked Door" policy (doors can only be opened from the inside)? 304 78.15% No 85 21.85% 31. Does your school have a "Check-In" policy for school visitors? 386 99.23% No 3 0.77% 32. Does your school have an established emergency response plan for dealing with school safety issues? 384 Yes 98.71% No 5 1.29% 33. Does your school have on-site security provided by police officers or private security guards? Yes 68 17.48% No 321 82.52% 34. Does your school have parent or other community volunteers to assist in monitoring the school? 73 Yes 18.77% No 316 81.23% 35. Does your school have metal detectors? Yes 23 5.91% No 366 94.09% 36. Does your school have surveillance cameras located within the school building or on school grounds? Yes 54 13.88% 86.12% No 335 C. EDUCATIONAL APPROPRIATENESS AND SUITABILITY **ELEMENTARY SCHOOLS ONLY** Number of Elementary Schools Reported: Educational Appropriateness: 38. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives. Strongly agree with statement: 37 12.71% Disagree with statement: 46 15.81% Agree with statement: 203 69.76% Strongly disagree with statement: 5 1.72% 39. Pre-kindergarten and Kindergarten space accommodates developmental range and needs of young children by providing a minimum of 35 square feet per occupant.

Strongly agree with statement: 49 16.96% Disagree with statement: 36 12.46%

Agree with statement: 198 68.51% Strongly disagree with statement: 6 2.08%

CESA: 01 Number of schools reported for CESA 01: 389 Number of Elementary Schools reported for CESA 01: 271 40. Adequate space is available for small work group instruction (less than 15 students). Strongly agree with statement: 33 11.42% Disagree with statement: 150 51.90% Agree with statement: 94 32.53% Strongly disagree with statement: 12 4.15% 41. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students. Strongly agree with statement: 53 18.34% Disagree with statement: 126 43.60% 103 Agree with statement: 35.64% Strongly disagree with statement: 7 2.42% 42. Adequate space is available for large work group instruction (more than 30 students). Strongly agree with statement: 25 8.65% Disagree with statement: 185 64.01% Agree with statement: 56 19.38% Strongly disagree with statement: 23 7.96% 43. Equipment and furniture (such as shelving units, tables, and chairs) are the appropriate size for the building's student population. Strongly agree with statement: 49 16.96% Disagree with statement. 9 3.11% Agree with statement: 231 79.93% Strongly disagree with statement: 0 0.00% **Building Suitability for Education:** 44. Buildings materials, color schemes, and decor provide impetus to learning. Strongly agree with statement: 38 13.15% Disagree with statement: 104 35.99% Agree with statement: 142 49.13% Strongly disagree with statement: 5 1.73% 45. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located. Strongly agree with statement: 52 17.99% Disagree with statement: 61 21.11% Agree with statement: 172 59.52% Strongly disagree with statement: 4 1.38% 46. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size. Strongly agree with statement: 32 11.07% Disagree with statement: 140 48.44% Agree with statement: 98 33.91% Strongly disagree with statement: 19 6.57% 47. Building is accessible to students with disabilities. Strongly agree with statement: 66 22.84% Disagree with statement: 75 25.95% Agree with statement: 118 40.83% Strongly disagree with statement: 30 10.38% 48. Space is available and appropriate for extended day learning opportunities, including before and after school day care. Strongly agree with statement: 33 11.50% Disagree with statement: 67 23.34% Agree with statement: 182 63.41% Strongly disagree with statement: 5 1.74% School Site Suitability: 49. Site is large enough to meet educational needs and is accessible. Strongly agree with statement: 47 16.26% Disagree with statement: 47 16.26% Agree with statement: 192 66.44% Strongly disagree with statement: 3 1.04%

Number of schools reported for CESA 01: 389 CESA: 01 Number of Elementary Schools reported for CESA 01: 271 50. Site has a safe outdoor space where children can engage in a variety of games, sports, and motor activities. Strongly agree with statement: 72 24.91% Disagree with statement: 10 3.46% Agree with statement: 196 67.82% Strongly disagree with statement: 11 3.81% 51. Student loading areas are segregated from other vehicular traffic and pedestrian walkways. Strongly agree with statement: 15 5.19% Disagree with statement: 132 45.67% Agree with statement: 112 38.75% Strongly disagree with statement: 30 10.38% Playground Site and Equipment Suitability: 52. Playground size is appropriate for number of students. Strongly agree with statement: 21.80% 63 Disagree with statement: 36 12.46% Agree with statement: 172 59.52% Strongly disagree with statement: 18 6.23% 53. Playgrounds are separated from streets and parking areas with fencing or other permanent material. Strongly agree with statement: 58 20.07% Disagree with statement: 54 18.69% Agree with statement: 161 55.71% Strongly disagree with statement: 16 5.54% 54. Playgrounds are well equipped and appropriate for age levels. Strongly agree with statement: 36 12.46% Disagree with statement: 23.88% 69 Agree with statement: 171 59.17% Strongly disagree with statement: 4.50% 13 55. Playground equipment is accessible to students with disabilities. Strongly agree with statement: 23 7.96% Disagree with statement: 104 35.99% Agree with statement: 138 47.75% Strongly disagree with statement: 24 8.30% 56. Playground equipment is free of sharp edges, of sound construction, and in good condition. Strongly agree with statement: 36 12.46% Disagree with statement: 41 14.19% Agree with statement. 199 68.86% Strongly disagree with statement: 13 4.50% MIDDLE, JUNIOR HIGH, AND HIGH SCHOOLS ONLY **Number of Secondary Schools Reported:** 118 Educational Appropriateness: 57. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives. Strongly agree with statement: 20 16.13% Disagree with statement: 35 28.23% Agree with statement: 69 55.65% Strongly disagree with statement: 0 0.00% 58. Size and design of special learning areas (science labs, art, technology education, music and special education) is compatible with instructional need. Strongly agree with statement: 24 19.35% Disagree with statement: 33 26.61% Agree with statement: 62 50.00% Strongly disagree with statement: 5 4.03% 59. Adequate space is available for small work group instruction (less than 15 students). Strongly agree with statement: 23 18.55% Disagree with statement: 37 29.84% Agree with statement: 61 49.19% Strongly disagree with statement: 3 2.42%

CESA: 01 Number of schools reported for CESA 01: 389 Number of Secondary Schools reported for CESA 01: 118 60. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students. Strongly agree with statement: 30 24.19% Disagree with statement: 31.45% Agree with statement: 55 44.35% Strongly disagree with statement: 0 0.00% 61. Adequate space is available for large work group instruction (more than 30 students). Strongly agree with statement: 10.48% Disagree with statement: 62 50.00% 40 32.26% Agree with statement: Strongly disagree with statement: 9 7.26% **Building Suitability for Education:** 62. Buildings materials, color schemes, and decor provide impetus to learning. Strongly agree with statement: 22 17.74% Disagree with statement: 36 29.03% Agree with statement: 61 49.19% Strongly disagree with statement: 5 4.03% 63. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located. Strongly agree with statement: 29 23.39% Disagree with statement: 12 9.68% Agree with statement: 81 65.32% Strongly disagree with statement: 2 1.61% 64. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size. Strongly agree with statement: 20 16.13% Disagree with statement: 21 16.94% Agree with statement: 81 65.32% Strongly disagree with statement: 2 1.61% 65. Building is accessible to students with disabilities. Strongly agree with statement: 21.77% 27 Disagree with statement: 17 13.71% Agree with statement: 75 60.48% Strongly disagree with statement: 5 4.03% 66. Space is available and appropriate for extended day learning opportunities, including before and after school day care. Strongly agree with statement: 17 13.71% Disagree with statement: 26 20.97% Agree with statement: 76 61.29% Strongly disagree with statement: 5 4.03% **School Site Suitability:** 67. Site is large enough to meet educational needs and is accessible. Strongly agree with statement: 20.97% 26 Disagree with statement: 24 19.35% Agree with statement: 71 57.26% Strongly disagree with statement: 3 2.42% 68. Site has a safe outdoor space where students can engage in a variety of games, sports, and motor activities. Strongly agree with statement: 24.19% Disagree with statement: 10 8.06% Agree with statement: 82 66.13% Strongly disagree with statement: 2 1.61% 69. Student loading areas are segregated from other vehicular traffic and pedestrian walkways. Strongly agree with statement: 9 7.26% Disagree with statement: 70 56.45% 21.77% Agree with statement: 27 Strongly disagree with statement: 18 14.52%